

PATENT
51278/C1015

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

I hereby certify that this correspondence is being electronically filed with the United States Patent and Trademark Office on May 12, 2010 at or before 11:59 p.m. Pacific Time under the Rules of 37 CFR § 1.8.


Signature

U.S. Patent No.	: RE40657	Confirmation No. 2547
Issued	: March 10, 2009	
Inventor(s)	: Dong Tack Suh	
Application No.	: 10/812,342	
Filed	: March 29, 2004	
Title	: PULL PIN ASSEMBLY FOR CANOPY	

REQUEST FOR CERTIFICATE OF CORRECTION

Office of Certificates of Correction
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

P. O. Box 7068
Pasadena, CA 91109-7068
May 12, 2010

Commissioner:

Submitted herewith is a copy of a proposed Certificate of Correction for the above-referenced patent. The errors are identified in detail in the proposed certificate, and the corresponding text in the application is located as follows:

Location in Patent

Location in Application

PTO errors:

Column 8, Claim 22, line 34

Amendment dated September 24, 2008,
page 7, old claim 38, line 9

Applicant errors:

Column 7, claim 19, line 39

Amendment dated September 24, 2008,
page 5, old Claim 23, line 1

U.S. Patent No. RE40657


Applicant's error was unintentional and inadvertent, and was made in good faith through oversight. Correction is accordingly requested under 35 U.S.C. § 255, and the statutory fee of \$100.00 is submitted herewith. Any deficiency or overpayment should be charged or credited to Deposit Account No. 03-1728. Please show our docket number with any credit or charge to our Deposit Account.

Correction of applicant's error does not constitute new matter or require reexamination. Approval of this certificate is respectfully requested.

Respectfully submitted,

CHRISTIE, PARKER & HALE, LLP

By


Tiffany A. Parcher
Reg. No. 58,944
626/795-9900

TP/smm

Enclosures: Certificate of Correction

TP PAS893581.1-*05/12/10 1:51 PM

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : RE40657
APPLICATION NO.: 10/812,342
ISSUE DATE : March 10, 2009
INVENTOR(S) : Dong Tack Suh

Page 1 of 1

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the Claims

Column 7, Claim 19, line 39 Before the word "resilient" insert the word -- the --

Column 8, Claim 22, line 34 After the word "bosses" delete the word "therein" and
insert the word -- thereon --

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Christie, Parker & Hale, LLP
P.O. Box 7068
Pasadena, CA 91109-7068

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.